DATA SHEET

Three Phase Induction Motor - Squirrel Cage

:



Customer

Insulation class Service factor	a (I)	: F : 1.15 : 0.4651 sq.ft lb				
Moment of inertia Design	a (J)	: 0.4651 sq.ft.lb : B				
Output		50% 75%	100%	Foundation loads		
Efficiency (%)		88.5 88.5 89.5 86. 87.3 87.3	9 89.5 83.9 85.6	Max. traction	: 273 lb	
Power Factor	0.46 0.52	0.73 0.80 0.83 0.8 0.71 0.82		Max. compression	: 399 lb	
		Drive		Non drive e		
Bearing type:6209 ZZSealing:Without Bearing Seal			6206 ZZ Without Bearing Seal			
Lubrication interv		:	-	-	.9 000	
Lubricant amoun Lubricant type	it	:	- 	- bil Polyrex EM		
nust be eliminate 1) Looking the m	ed. otor from the			These are average value power supply, subject to MG-1.		
nust be eliminate 1) Looking the m 2) Measured at 1 3) Approximate v nanufacturing pro	ed. lotor from the lm and with f weight subjec ocess.		A).	power supply, subject to		
nust be eliminate 1) Looking the m 2) Measured at 1 3) Approximate v nanufacturing pro 4) At 100% of ful	ed. lotor from the lm and with f weight subjec ocess.	e shaft end. tolerance of +3dB(/ ct to changes after	A).	power supply, subject to MG-1.	the tolerances stipul	lated in NEMA
nust be eliminate 1) Looking the m 2) Measured at 1 3) Approximate v nanufacturing pro 4) At 100% of ful Rev.	ed. lotor from the lm and with f weight subjec ocess.	e shaft end. tolerance of +3dB(/ ct to changes after	A).	power supply, subject to MG-1.	the tolerances stipul	lated in NEMA
nust be eliminate (1) Looking the m (2) Measured at 1 (3) Approximate v manufacturing pro (4) At 100% of ful	ed. lotor from the lm and with f weight subjec ocess.	e shaft end. tolerance of +3dB(/ ct to changes after	A).	power supply, subject to MG-1.	the tolerances stipul	lated in NEMA

Subject to change without notice